



Robert Monsignore Services

LEAK DETECTION - VIDEO PIPE INSPECTION
FULL SERVICE PLUMBING & DRAIN CLEANING



954-709-7139



INVOICE # 623-75		INVOICE DATE 6/23/2025	
Home Phone		Business Phone	
Bill To COUNTRY CLUB TOWER			
Address 10777 WEST SAMPLE ROAD			
City CORAL SPRINGS FL. 33065			
Mechanic ROBERT		Helper	
Description of Work		Total	
1 CONDENSATION PUMP		\$70.00	
WE INSTALLED A CONDENSATION PUMP FOR THE EXERCISE ROOM AIR HANDLER.		\$115.00	
Total Due		\$185.00	
TERMS: DUE UPON COMPLETION I have the authority to order the above work and do so order as outline above. It is agreed that the seller will retain title to any equipment or material furnished until final and complete payment is made, and if settlement is not made as agreed. The seller shall have the right to remove same and the seller will be held harmless for any damages resulting from the removal thereof.		PARTS & LABOR Warranty All parts and labor are warranted for a period of 30 days. We do not of course other parts than those we install. If repairs later become necessary due to other defective parts, they will be charged separately.	

X _____

Authorized Signature

Above ordered work has been completed and I acknowledge receipt of my copy

v